

From: ["Way, Steven" </O=EXCHANGELABS/OU=EXCHANGE ADMINISTRATIVE:GROUP \(FYDIBOHF23SPDLT\)/CN=RECIPIENTS/CN=2BA46A1DF61E4411A1C7883BB30E0BC5-WAY,STEVEN>](mailto:Way.Steven@EXCHANGELABS/OU=EXCHANGE ADMINISTRATIVE:GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=2BA46A1DF61E4411A1C7883BB30E0BC5-WAY,STEVEN)
To: Roberts
["Kris D." <kroberts@nd.gov>](mailto:kroberts@nd.gov)
CC:
Date: 1/9/2015 1:58:43 PM
Subject: Williston Produced Water Spill - Little Muddy

Kris,

If you would, please send me whatever the you guys have on this situation. I contacted the RP (Summit Midstream Partners) today and did not get any useful information. My assumption is that it's pretty sizeable lead if they're already sampling the Little Muddy, which he indicated.

Also, is there any significant oil content observed or is it just the produced / brine water ?

Let me know if you think some assistance is needed. I understand that the RP has a contractor onsite, supposedly pumping water from the creek, but if there is more they need to do let me know.

Thanks,
Steve

Steven Way
Federal On-Scene Coordinator
Emergency Response Unit
US EPA - Region 8
1595 Wynkoop Street
Denver, CO 80202

Office: 303-312-6723